

General Environmental Incident Summary

Incident: 3889 **Date/Time Notice:** 9/2/2015 2156 **DEM Incident No:**
Responsible Party: Halliburton

Date Incident: 9/2/2015 **Time Incident:** 0245 **Duration:** 1 hours

County: McKenzie **Twp:** 151 **Rng:** 95 **Sec:** 36 **Qtr:**

Lat: 47.85799 **Long:** -102.78940 **Method:** Interpolation from map

Location Description: SHD Oil & Gas, LLC
Magnum and Avalanche Well Site
Clark Creek Field
McKenzie County, North Dakota
NW ¼ Section 36 T151N R95W

Submitted By: Randy Neset **Affiliation:** SHD Oil & Gas, LLC

Address: 6844 Highway 40

6844 Highway 40

City: Tioga

State: ND

Zip: 58852

Received By:

Contact Person:

420 Halliburton Drive

Williston, ND 58801

Distance Nearest Occupied Building: 5 Miles **Release Contained:** Yes

Type of Incident: Hose on tote deteriorated

Description of Released Contaminant: Hypochlorite solution

Volume Spilled: 319.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Hose attached to tote containing hypochlorite solution deteriorated causing spill.

Risk Evaluation:

No immediate hazardous risk.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

There are no potential environmental impacts . Affected media (scoria) has been removed

Action Taken or Planned:

The spill was contained and immediately spill adsorbent pads were used to absorb any of the hypochlorite solution that was on the scoria well pad base. Thereafter, Clean Harbors Environmental Services responded and removed any effected scoria. Approximately, six inches of material was removed from the effected area and taken to Sawyer Landfill in Sawyer, ND for disposal.

Wastes Disposal Location: Clean Harbor Sawyer Industrial Landfill in Sawyer, ND

Agencies Involved: BLM, North Dakota State Trust Land

Updates

Date: 9/3/2015

Status: Reviewed; O&G Lead

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, the spill was contained and remained on the well pad site. Report forwarded to NDIC for further followup.